



| <b>Pour vis</b>   |                         | $d_1$ | $d_2$ | s   |
|-------------------|-------------------------|-------|-------|-----|
| <b>For screws</b> |                         | min.  | max.  |     |
| <b>M</b>          | <b>2<sup>1)</sup></b>   | 2,2   | 4     | 0,5 |
|                   | <b>2,5<sup>1)</sup></b> | 2,7   | 5     | 0,5 |
|                   | <b>3</b>                | 3,2   | 6     | 0,8 |
|                   | <b>4</b>                | 4,3   | 8     | 0,8 |
|                   | <b>5</b>                | 5,3   | 10    | 1   |
|                   | <b>6</b>                | 6,4   | 12    | 1,2 |
|                   | <b>(7)</b>              | 7,4   | 14    | 1,5 |
|                   | <b>8</b>                | 8,4   | 16    | 1,5 |
|                   | <b>10</b>               | 10,5  | 20    | 2   |
|                   | <b>12</b>               | 13    | 24    | 2,5 |
|                   | <b>(14)</b>             | 15    | 27    | 2,5 |
|                   | <b>16</b>               | 17    | 30    | 3   |
|                   | <b>(18)</b>             | 19    | 32    | 3   |
|                   | <b>20</b>               | 21    | 36    | 3   |
|                   | <b>(22)</b>             | 23    | 40    | 3   |
| <b>24</b>         | 25                      | 45    | 4     |     |
| <b>(27)</b>       | 28                      | 48    | 4     |     |
| <b>30</b>         | 31                      | 52    | 4     |     |